Welding Metallurgy Distortion Residual Stress & Post-Weld Heat Treatment


#### **Lecture Scope**

 Typical patterns of distortion & residual stress in welded assemblies

<u>\_\_\_\_</u>

\_\_\_\_\_


- Effects of residual stress
- Methods for prevention and correction of distortion
- Heat treatment of steel weldments





### **Causes of Residual stress**

- During welding, the weld and HAZ are heated to temperatures well above those of the surrounding material
- The weld and HAZ deform plastically because their thermal expansion is resisted by the surrounding material
- As the weld cools and contracts, tensile stresses develop elastically
- Welds contain tensile stresses that approach the yield stress.


p4








1
·······
·······



	· _ · _ ~ _ ~			
······			· · · · · · · · · · · · · · · · · · ·	
		· · · · · · · · · · · · · · · · · · ·		
		······································		
		· · · · · · · · · · · · · · · · · · ·		
				······
. 40				- 0




······································	 ·····	 
······	 	 

# **Restraint Stresses**

- When the workpiece is free to expand or contract, residual stresses are confined to the region of the weld
- When the workpiece is restrained, e.g. between rigid anchors, long-range reaction stresses develop

p 10



### **Effects of Residual Stress**


- Residual stresses do not affect the load carrying capacity of ductile materials that fail by yielding
- Residual stresses may promote failure mechanisms that are sensitive to localized stresses
  - fatigue
  - brittle fracture
  - stress corrosion cracking
  - creep cracking

# **Control of Residual Stress**

- Use minimum required weld size and heat input
  J or U preparations give smaller weld areas
- Minimise constraint during welding
- Stress relief
  - Heat treatment
  - Mechanical e.g. vibratory


## Distortion

- Distortion in welded fabrications is caused by movements to accommodate thermal stresses
- Distortion in welded fabrications consists of:
  - transverse shrinkage
  - longitudinal shrinkage
  - angular rotations
- Distortion is a problem mostly with thinner materials




		······································	
	······································		
	· · · · · · · · · · · · · · · · · · ·	······	
· · · · · · · · · · · · · · · · · · ·			
		····	


<u></u>	ł				
	1. Angular Rot		2. Bending cau weld shrinkage from neutral ax section	offset	
		· · · · · · · · · · · · · · · · · · ·			
		· · · · · · · · · · · · · · · · · · ·			




				· · · · · · · · · · · · · · · · · · ·		·	
		· ··	······································		··		
	· · · · · · · · · · · · · · · · · · ·						<u> </u>
	· ····································						
·	· · · · · · · · · · · · · · · · · · ·						_




-----



		······································	·········	······································	
		·			
	· · · · · · · · · · · · · · · · · · ·				
<u></u>					
	······································	· · · · · · · · · · · · · · · · · ·			
	<u></u>	···· · <u>·····</u>			,
	· · · · · · · · · · · · · · · · · · ·	·····			





	 · · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·
	 	·	
	 	<u> </u>	
······································	 		
· · · · · · · · · _ · _ ·	 	······································	
·····	 		

# **Heat Treatment of Welds**

- Heat treatment is costly and should be avoided unless necessary for satisfactory performance
- May be required by applicable codes and standards

## **Weld Heat Treatments**

#### Preheating

- Heating prior to welding, usually to temperatures less than 200C
- Applied in welding C-Mn steels to decrease cooling rates and reduce HAZ hardness
- Not generally required for stainless steels. nickel alloys, titanium zirconium or aluminum

#### Post Weld Heat Treatment


- Heating after welding to relieve stresses, refine weld grain structure, or improve weld properties

Lecture 10


# **Post Weld Heat Treatment**


- Definitions
  - Stress Relief
    - Heating to a temperature (usually around 600C) at which the yield strength is reduced such that residualstresses are relieved
  - Normalizing
    - Heating to above the temperature for transformation to austenite (A3) and slow cooling for to refine and homogenize the grain structure
  - Quenching
    - Heating as in normalizing and rapid cooling in water, brine or air to develop high strength.

ŧ,



# **PWHT Methods**





 	······	 
 ··		
 · · · · · · · · · · · · · · · · · · ·		 