

Weld Quality

WELD DISCONTINUITIES

Lecture Scope

- **Nature & causes of discontinuities in steel fusion welds**
- **Significance for weld fitness-for-service**
- **Preventive measures**

Weld Discontinuities

- Weld discontinuities are interruptions of the typical structure of a weldment such as a lack of continuity in its physical, metallurgical or mechanical characteristics
- Discontinuities may be found in the weld metal, the heat affected zone and the base metal.
- Discontinuities that exceed established acceptance standards are termed "defects"

Causes of Weld Discontinuity

- Discontinuities can be thought of as originating in two sets of causes:
 1. **Technological**: related to metallurgy and welding process
 2. **Execution**: related to welding operator skill in implementing procedures etc.


Types of Weld Discontinuity

- Discontinuities are usually classified according to their physical characteristics

Type	Location	Fig Ref
Cracks	W, HAZ	12
Laminations, seams and laps	BM	8,9,10
Lamellar tears	BM	11
Porosity/Cavities	W	1
Inclusions	W	2
Lack of fusion or penetration	W	3,4
Imperfect shape: undercut, overfill, overlap	BM, W, W	5, 6, 7

W= weld
HAZ=heat affected zone
BM=base metal

Weld Defects: Groove Weld



Lecture 12

FAULTS IN FUSION WELDS IN CONSTRUCTIONAL STEELS

Edited by Norman Bailey

Slide set number 2

Published by The Welding Institute,
Abington Hall, Abington,
Cambridge CB1 6AL, UK

© 1975, 1979, 1986

First published 1972
Second edition 1986

ISBN 0 85300207 X

This set of photographs illustrates the main faults found in fusion welds in constructional steels. The notes in this booklet provide a brief identification and description of the faults illustrated; they do not attempt to provide a comprehensive text.

Terms relating to weld imperfections are defined in British Standard BS 499: Part 1: 1983. The examples have been chosen to illustrate the defects, and do not indicate acceptance levels, for which see the appropriate product standards.

Each section has notes on causes, and where appropriate, on rectification and on prevention.

Most of the photographs also appear in The Welding Institute wallchart, 'Faults in fusion welds in constructional steels' (Ref. C1-86).

CAUSES

Common causes of faults in welds made by the conventional arc welding processes are briefly described.

RECTIFICATION

Measures to remove the defect, if it exceeds the applicable acceptance criteria, are outlined.

PREVENTION

Preventive measures, where they do not consist simply of an obvious treatment of the cause, are outlined.

Some joints call for considerable welder skill to obtain an acceptable weld; in these cases, preventive measures may involve selection, training, and approval testing of welders.


DETECTION

Surface defects are normally detected by visual inspection, penetrant dye or magnetic particle inspection: in some cases it is feasible to use eddy current or potential drop testing.

To detect embedded defects, volumetric methods, principally radiography and ultrasonics, are needed: they also indicate surface defects. The performance of either method depends critically on orientation of the defect to the beam: this must be taken into account when selecting a test procedure.

SLIDE SET 2

The photographs are also available as a slide set, numbered 0240 to 0279. Each slide carries its number in the picture area, repeated on the slide mount and indicating correct orientation.



INDEX

CRACKS

	page
0241, 0242 Solidification cracking	6
0243 Hydrogen-induced HAZ cracking	8
0244, 0245, 0246 Hydrogen-induced weld metal cracking	10
0247, 0248 Lamellar tearing	12
0249, 0250 Reheat cracking	14

CAVITIES

0251, 0252, 0253 Wormholes	16
0254, 0255 Uniform porosity	18
0256 Restart porosity	20
0257 Surface porosity	21
0258 Crater pipes	22
0259 Microporosity	23

INCLUSIONS

0260 Linear inclusions	25
0261, 0262 Isolated inclusions	26

LACK OF FUSION AND PENETRATION

0263 Lack of side fusion	29
0264 Lack of inter-run fusion	30
0265 Lack of root fusion	30
0266, 0267 Incomplete root penetration	31

IMPERFECT SHAPE


0268 Linear misalignment	32
0269 Excess weld metal	33
0270 Overlap	34
0271 Undercut	35
0272, 0273 Excess penetration bead	36
0274, 0275 Root concavity	38

MISCELLANEOUS FAULTS

0276 Stray arcing	40
0277 Spatter	41
0278 Copper pickup	42
0279 Surface pocking	43

CRACKS

SOLIDIFICATION CRACKING



CAUSES

Excessively deep or wide weld bead.

High current and/or welding speed.

Large root gap.

Carbon, sulphur or phosphorus pickup from parent steel.

The risk of cracking is greatest with submerged-arc welding, and reduced with gas-shielded metal-arc, self-shielded metal arc, manual metal arc, to least with gas-shielded tungsten-arc.

High strength parent metal increases the risk.

RECTIFICATION

Cut out defective weld length plus 5mm beyond visible end of crack and reweld.

PREVENTION

Plan welding parameters to reduce thermally induced strains.

Adjust weld parameters to obtain weld width between 0.5 and 0.8 of depth.


Avoid parent steels containing more than 0.6% total of sulphur and phosphorus.

Take care if submerged-arc welding steel with more than 0.2% carbon.

Clean off all traces of cutting oils.

Control joint fit-up to reduce gaps.

Reduce weld metal dilution by reducing welding current, by welding with electrode negative, or in the submerged-arc process with metal powder additions.



CAUSES

Hardened HAZ — heat affected zone of the parent metal — coupled with presence of hydrogen diffused from weld metal, caused by damp electrodes or flux, or contaminated wire.

Susceptibility increases with increasing thickness of section, especially in steels with high carbon equivalent.

Excessively fast cooling, allowing insufficient time for hydrogen to diffuse out at higher temperatures — cracking does not occur above about 200°C.

High restraint, excessive root gaps, stress concentrations.

Risk greatest with manual metal arc welding with cellulosic or rutile electrodes; least with gas-shielded tungsten-arc, solid wire gas-shielded metal-arc and manual metal arc with austenitic or nickel-base or adequately dried and controlled basic electrodes. NOTE: the cracks are fine and difficult to detect; they may not be found until after postweld heat treatment. They grow slowly, so inspection should be delayed.

RECTIFICATION

Short isolated lengths of crack, where accessible, can be cut out and rewelded. Extensive or inaccessible cracking may not be possible to rectify. Austenitic or nickel-base electrodes may be helpful if preheat must be limited. Note that any repair weld should use the correct procedures as detailed below.

PREVENTION

Use the appropriate procedures, which may include:

Hydrogen-controlled welding consumables;


Consumables dried and stored in accordance with the manufacturer's instructions;

Preheat and minimum interpass temperatures reaching the specified value in the whole joint;


Heat input as specified, even for tack welds;

Parent metal composition within limits specified for the procedure in use.


Avoid use of excessively strong weld metal.



Weld face, toes at the sides of the photograph



Weld face, toes at top and bottom of photograph



May be transverse (0244), at 90° or 45° to surface (0245), or longitudinal (0246).

CAUSES

Weld metal alloyed as much as, or more than, parent steel, usually in thick sections with insufficient consumable drying or preheat.

High restraint.



Excessive gap.

Sharp notch in root run.

PREVENTION

As for HAZ cracking.

LAMELLAR TEARING



Fracture surface

CAUSES

Poor ductility in through-thickness direction because of non-metallic inclusions.

Only found in rolled plate.

Occurs mainly where weld metal is deposited on plate surface, such as T, corner, and cruciform joints, and where restraint is high.

RECTIFICATION


Gouge out cracked area. Butter affected plate with low strength weld metal to spread residual stresses over a large area.

PREVENTION

Design joints to avoid through-thickness tensile stress.

Specify plate with sufficient through-thickness (short transverse) ductility, that is with a low sulphur and oxygen content.

Use forgings or castings instead of plate.



treatment, particularly if they contain chromium, molybdenum and vanadium.


CAUSES

Poor creep ductility in HAZ coupled with thermal stress. Accentuated by severe notches such as pre-existing cracks, or tears at weld toes, or unfused root of partial penetration weld.

PREVENTION


Heat treatment may need to include low temperature soaking, followed by fairly rapid heating to final temperature. Grinding or peening of weld toes after welding can be beneficial.

Can be avoided by 'two-layer' welding technique to refine the coarse-grained heat affected zone, together with the use of non-susceptible weld metal.



CAVITIES

WORMHOLES



0251  © The Welding Institute UK 1975

20mm


Radiograph



0252  © The Welding Institute UK 1975

10mm

Radiograph




Fracture surface


Resulting from entrapment of gas between solidifying dendrites of weld metal, often showing a 'herring-bone' array, as in radiograph 0252.

CAUSES

The gas may arise from contamination of surfaces to be welded, or be prevented from escaping from beneath the weld by joint crevices.



Radiograph



CAUSES

Gas may originate from dampness or grease on consumables or workpiece, or by nitrogen contamination from the atmosphere. If the welding wire used contains insufficient deoxidant it is also possible for carbon monoxide to cause porosity.

PREVENTION


Remove the sources of gas by avoiding or removing contamination.

Ensure correct shielding gas flow.

Use consumables with higher levels of deoxidants.

Where porosity is the result of an intentional surface treatment, such as priming paint, remove it locally.

RESTART POROSITY



Radiograph

CAUSES


Unstable arc conditions at weld start, where protection may be incomplete and temperature gradients have not had time to equilibrate, coupled with inadequate manipulative technique to allow for this instability.

The radiograph shows internal restart porosity.

PREVENTION

Improve the welder's restart technique.
Start on a run-on tab if practicable.

SURFACE POROSITY



CAUSES


Excessive contamination from grease, dampness, or atmospheric entrainment.

Occasionally caused by excessive sulphur in consumables or parent metal.

PREVENTION

As for uniform porosity.

Reduce sulphur content where appropriate.



Resulting from shrinkage at the end crater of a weld run.

CAUSES


Incorrect manipulative technique or current decay to allow for crater shrinkage.

PREVENTION

Improve welder's technique.

Use a welding set with a current decay facility.

Use a run-off tab.



Resulting from shrinkage at, or just below, the surface of a submerged-arc weld.

CAUSES

High welding speed with deep weld pool.

INCLUSIONS

LINEAR INCLUSIONS





Radiograph

CAUSES

Incomplete removal of slag in multipass welds, often associated with the presence of undercut or irregular surfaces in underlying passes. The radiograph in the slide shows two slag lines in a weld root zone.

prepared surfaces, or electrodes with coverings which are cracked or damaged, for example by too rapid drying. May also arise from isolated undercut in underlying passes of multipass welds.



Radiograph


LACK OF FUSION AND PENETRATION

CAUSES

Incorrect welding conditions, such as too low a current, or incorrect torch/gun angle.

Incorrect edge preparation, for example too large a root face.

LACK OF SIDE FUSION





0264  © The Welding Institute UK 1975 5mm


LACK OF ROOT FUSION



0265  © The Welding Institute UK 1986 2mm



0266  © The Welding Institute UK 1975 20mm




0267  © The Welding Institute UK 1975 10mm

Radiograph

IMPERFECT SHAPE

LINEAR MISALIGNMENT



0268  © The Welding Institute UK 1975

50mm

CAUSES

Incorrect assembly and/or distortion during fabrication.

EXCESS WELD METAL

Alternative term — REINFORCEMENT



0269  © The Welding Institute UK 1975

50mm

Weld metal normally extends above the parent metal surface: only a fault if exceeding specification.

CAUSES

Deposition of too much weld metal, often associated with unsuitable weld preparation, incorrect welding parameters, or too large an electrode.



0270



© The Welding Institute UK 1975

20mm

CAUSES

Poor manipulative technique or insufficient heat input, with current or voltage too low.
Depositing too large a fillet weld run in the horizontal-vertical position.



0271



© The Welding Institute UK 1975



20mm

Results from washing away of the edge preparation when molten.

CAUSES

Poor welding technique and/or unbalanced welding conditions.

EXCESS PENETRATION BEAD





Weld metal normally extends below the parent metal surface: only a fault if exceeding specification.

CAUSES


Incorrect edge preparation providing insufficient support at the root, and/or incorrect welding parameters.

May also be caused by incorrect welding technique, or too high a gas backing pressure.



MISCELLANEOUS FAULTS

STRAY ARCING



CAUSES


Accidental contact of electrode or welding torch with plate surface remote from weld. These usually result in small hard spots just beneath the surface which may contain cracks, and are thus to be avoided.

SPATTER




CAUSES

Incorrect welding conditions, such as too high a welding current, and/or contaminated consumables or preparations, giving rise to explosions within the arc and weld pool. Globules of molten metal are thrown out, and adhere to the parent metal remote from the weld.



CAUSES

Melting of copper contact tube in gas-shielded metal-arc welding because of incorrect welding conditions.



Surface depression on face of submerged-arc weld.

CAUSES

Flux inadequately dried or containing insufficient deoxidants.