#### Transformers

\_\_\_\_


**E** 

# **Transformer Ratings**

- VA rating
- Cooling
  - 1000 kVA 55°C ONAN
- Frequency
- Voltage
- Phase





## Separate Windings







#### Autotransformer














## On Load Tap-Changers

































(10)

Tap-Changer Sequence of Operation

## Transformer Losses


- No-Load
  - Hysteresis
  - Eddy Currents
  - A tiny winding loss due to exciting current
- Winding Losses
  - Vary with the square of the load

## Copper Losses




#### Core Losses


\_\_\_\_




#### Laminated Core



### Transformer Hot Spot



### Core Heating



## Instrument Transformers

- Step down values to safe levels for measurement
- Potential Transformers
  - Also called voltage transformers
  - Standard output 120V
- Current Transformers
  - Standard output of 1 or 5 amps
  - Metering and relaying standards
  - Can produce high voltages if open circuited



### You do the Questions







